

Dear OXY GoM Contactor,

The following must be completed within ISNetworld for all contractor employees performing offshore work for OXY, or they will scan RED.

For Offshore Contractor Employees, each employee MUST be qualified and up to date in ISNetworld for the below 7 TQ course requirements:

1. **Marine Trash and Debris** (*only one of the below trainings is required*)
 1. BSEE 001 – Marine Trash & Debris
 2. GNV 017 – Marine Trash and Debris (NTL 2015-G03 - Marine Trash and Debris Awareness and Elimination) – *Entered by your company in ISNetworld*
2. **Water Survival with HUET*** (*only one of the below trainings is required*) – *Please note that we are also looking at CA-EBS certificates in conjunction with these water survival courses*
 1. GNV 025 Water Survival with HUET & Swing Rope Transfer – *Entered by your company in ISNetworld*
 2. GNV 042 – Water Survival with Huet – *Entered by your company in ISNetworld*
3. **GNV 019** – Offshore Safety Awareness/Orientation (*Industry endorsed/accredited course such as **Safe Gulf or Rig Pass***) – *Entered by your company in ISNetworld*
4. **OXY 017** – Job Specific Skills/Knowledge Verification – *Entered by your company in ISNetworld*
5. **OXY 018** – Moxie Media X904 Rider (*Online Training*) – OXY USA Inc.
6. **OXY 019** – Safe Swing Rope (*Online Training*) – OXY USA Inc.
7. **OXY GoM – HSE Orientation** (*only one of the below trainings is required*)
 1. **OXY 020** – OXY GoM Orientation *English* (Online Training) – OXY USA Inc.
 2. **OXY 021** – OXY GoM Orientation *Spanish* (Online Training) – OXY USA Inc.

OXY 018, 019, 020 & 021 qualifications are all online trainings available to complete in ISNetworld. Please reference the attached QRG to assign these trainings to your employees and provide instructions for them to complete.

We have also further updated our Training Qualifications (TQ) matrix to require the below Subpart O and Production Safety Systems Training certificates for applicable employees.

1. **TQ REV 211** – Well Servicing – Supervisor Level (30 CFR Subpart O)
2. **TQ REV 212** – Well Servicing – Introductory Level (30 CFR Subpart O)
3. **TQ REV 231** – Well Control – Introductory Level (30 CFR Subpart O)
4. **TQ REV 232** – Well Control – Supervisory Level (30 CFR Subpart O)
5. **TQ REV 214** – Production Safety Systems (30 CFR Subpart O)

To upload these certificates for your employees, please first assign them to one of the below Training Qualification Activities in ISNetworld. The activity you assign is determined by their type of work / which trainings they have completed.

- Offshore Contractor Employee – Well Servicing
- Offshore Contractor Employee – Well Control

Thank you in advance for your cooperation.

Sincerely,

HSE – AMS/SEMS/CSM Manager
OXY – GOM Business Unit